

EXTERIOR WINDOW GUARD SCHEDULE												
WINDOW GUARD NUMBER	WINDOW NUMBER	WINDOW GUARD & SECURITY SCREEN DESCRIPTION					WINDOW GUARD & SECURITY SCREEN DETAILS					REMARKS
		TYPE	MATERIAL	WINDOW ELEV.	MASONRY OPENING		DETAILS/SHEET					
					WIDTH	HEIGHT	HEAD	JAMB	SILL	MULLION		
CELLAR FLOOR												
C01	C01	SB	STL	C	5'-5"	5'-11"	A/A941	B/A941	A/941	C/A941		
C02	C02	SB	STL	C	5'-5"	5'-9"	A/A941	B/A941	A/941	C/A941		
C03	C03	SB	STL	C	5'-5"	5'-9"	A/A941	B/A941	A/941	C/A941		
C04	C04	SB	STL	G	8'-2"	6'-10"	A/A941	B/A941	A/941	C/A941		
C05	C05	SB	STL	C	10'-2"	6'-10"	A/A941	B/A941	A/941	C/A941		
C06	C06	SB	STL	G	4'-6"	6'-10"	A/A941	B/A941	A/941	C/A941		
BASEMENT FLOOR												
B01	B01	WI	WI	L	6'-7"	4'-0"	A942	A942	A942	-		
B02	B02	EG/WI	STL/WI	I	5'-5"	10'-1"	A942	A942	A942	-	Ventilator installed at top sash.	
B03	B03	EG/WI	STL/WI	I	5'-5"	10'-1"	A942	A942	A942	-		
B04	B04	EG/WI	STL/WI	I	4'-5"	10'-2"	A942	A942	A942	-		
B05	B05	EG/WI	STL/WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B06	B06	EG/WI	STL/WI	I	5'-5"	10'-2"	A942	A942	A942	-	HVAC, exhausting at bottom sash	
B07	B07	EG/WI	STL/WI	I	5'-5"	10'-2"	A942	A942	A942	-	HVAC, exhausting at bottom sash	
B08	B08	EG/WI	STL/WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B09	B09	EG/WI	STL/WI	M	5'-5"	5'-10"	A942	A942	A942	-		
B10	B10	EG/WI	STL/WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B11	B11	WI	WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B12	B12	WI	WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B13	B13	WI	WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B14	B14	WI	WI	I	4'-5"	10'-2"	A942	A942	A942	-		
B15	B15	WI	WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B16	B16	WI	WI	I	5'-5"	10'-2"	A942	A942	A942	-		
B17	B17	WI	WI	L	6'-7"	4'-0"	A942	A942	A942	-		
B18	B18	WI	WI	J	13'-6"	10'-2"	A942	A942	A942	-		
B19	B19	WI	WI	N	8'-2"	5'-2"	A942	A942	A942	-		
B20	B20	WI	WI	K	9'-2"	10'-2"	A942	A942	A942	-		
B21	B21	WI	WI	L	6'-10"	2'-9"	A942	A942	A942	-		
B22	B22	WI	WI	K	9'-2"	10'-2"	A942	A942	A942	-		
B23	B23	WI	WI	N	8'-3"	4'-10"	A942	A942	A942	-		
B24	B24	WI	WI	J	13'-11"	10'-2"	A942	A942	A942	-		
B25	B25	WI	WI	O	6'-3"	3'-6"	A942	A942	A942	-		
B26	B26	WI	WI	O	6'-3"	3'-6"	A942	A942	A942	-		
B27	B27	WI	WI	J	13'-4"	10'-1"	A942	A942	A942	-		
B28	B28	WI	WI	N	8'-3"	5'-3"	A942	A942	A942	-		
B29	B29	WI	WI	K	8'-3"	10'-2"	A942	A942	A942	-		
B30	B30	WI	WI	K	8'-3"	10'-2"	A942	A942	A942	-		
B31	B31	WI	WI	K	8'-3"	10'-2"	A942	A942	A942	-		
B32	B32	WI	WI	N	8'-3"	5'-1"	A942	A942	A942	-		
B33	B33	WI	WI	J	13'-5"	10'-2"	A942	A942	A942	-		
FIRST FLOOR												
101	117	SB	STL	A	15'-5"	9'-5"	A/A941	B/A941	A/941	C/A941		
105	118	SB	STL	C	4'-5"	7'-5"	A/A941	B/A941	A/941	C/A941		
106	119	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
107	120	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
108	121	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
109	122	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
110	123	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
111	124	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
112	125	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
113	126	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
114	127	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
115	128	SB	STL	C	5'-5"	7'-5"	A/A941	B/A941	A/941	C/A941		
118	129	SB	STL	A	15'-5"	9'-5"	A/A941	B/A941	A/941	C/A941		
SECOND FLOOR												
201	221	SB	STL	A	13'-5"	9'-5"	A/A941	B/A941	A/941	C/A941		
202	222	SB	STL	C	4'-5"	7'-5"	A/A941	B/A941	A/941	C/A941		
203	223	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
204	224	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
205	225	SB	STL	B	5'-5"	10'-4"	A/A941	B/A941	A/941	C/A941		
206	226	SB	STL	B	5'-5"	10'-3"	A/A941	B/A941	A/941	C/A941		
207	227	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
208	228	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
209	229	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
210	230	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
211	231	SB	STL	B	5'-5"	10'-2"	A/A941	B/A941	A/941	C/A941		
212	232	SB	STL	C	4'-5"	7'-6"	A/A941	B/A941	A/941	C/A941		
213	233	SB	STL	A	15'-6"	9'-4"	A/A941	B/A941	A/941	C/A941		

INTERIOR WINDOW GUARD SCHEDULE												
WINDOW GUARD NUMBER	WINDOW NUMBER	WINDOW DESCRIPTION					WINDOW DETAILS					REMARKS
		TYPE	MATERIAL	WINDOW ELEV.	MASONRY OPENING		DETAILS/SHEET					
					WIDTH	HEIGHT	HEAD	JAMB	SILL	MULLION		
BASEMENT FLOOR												
B01	B04	IG	STL	I	4'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B02	B05	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B03	B06	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943	HVAC, exhausting at bottom sash	
B04	B07	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943	HVAC, exhausting at bottom sash	
B05	B08	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B06	B10	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B07	B11	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B08	B12	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B09	B13	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B10	B14	IG	STL	I	4'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B11	B15	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B12	B16	IG	STL	I	5'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B13	B18	IG	STL	J	13'-6"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B14	B20	IG	STL	K	9'-2"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B15	B22	IG	STL	K	9'-2"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B16	B33	IG	STL	J	13'-4"	10'-1"	A/A943	B/A943	A/A943	C/A943		
B17	B35	IG	STL	K	8'-3"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B18	B36	IG	STL	K	8'-3"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B19	B37	IG	STL	K	8'-3"	10'-2"	A/A943	B/A943	A/A943	C/A943		
B20	B39	IG	STL	J	13'-5"	10'-2"	A/A943	B/A943	A/A943	C/A943		
FIRST FLOOR												
101	102	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
102	108	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
103	111	IG	STL	E	8'-4"	9'-6"	A/A943	B/A943	A/A943	C/A943		
104	113	IG	STL	E	7'-10"	9'-4"	A/A943	B/A943	A/A943	C/A943		
105	115	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
106	118	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
107	128	IG	STL	C	5'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
108	131	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
109	135	IG	STL	E	8'-2"	9'-5"	A/A943	B/A943	A/A943	C/A943		
SECOND FLOOR												
201	202	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
202	212	IG	STL	C	4'-5"	7'-4"	A/A943	B/A943	A/A943	C/A943		
203	215	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
204	216	IG	STL	E	9'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
205	219	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
206	222	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
207	232	IG	STL	C	4'-5"	7'-6"	A/A943	B/A943	A/A943	C/A943		
208	235	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
209	239	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
THIRD FLOOR												
301	302	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
302	312	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
303	315	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
304	316	IG	STL	E	9'-2"	9'-4"	A/A943	B/A943	A/A943	C/A943		
305	319	IG	STL	E	8'-5"	9'-5"	A/A943	B/A943	A/A943	C/A943		
306	322	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
307	332	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
308	335	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
309	339	IG	STL	E	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
FOURTH FLOOR												
401	402	IG	STL	C	4'-4"	6'-8"	A/A943	B/A943	A/A943	C/A943		
402	412	IG	STL	C	4'-4"	6'-7"	A/A943	B/A943	A/A943	C/A943		
403	415	IG	STL	G	9'-2"	6'-10"	A/A943	B/A943	A/A943	C/A943		
404	419	IG	STL	G	8'-4"	7'-2"	A/A943	B/A943	A/A943	C/A943		
405	422	IG	STL	C	4'-5"	7'-2"	A/A943	B/A943	A/A943	C/A943		
406	432	IG	STL	C	4'-5"	7'-5"	A/A943	B/A943	A/A943	C/A943		
407	435	IG	STL	G	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		
408	439	IG	STL	G	8'-3"	9'-5"	A/A943	B/A943	A/A943	C/A943		

President & CEO
Lorraine Grillo

Board of Trustees
Chancellor Richard A. Carranza, Chairman
Curtis A. Harris
Emily A. Youssouf



Architecture & Engineering

E. Bruce Barrett, R.A. LEED A.P., Vice President
Elon R. Abner, P.E., Senior Director, Design Consultant Management
Stanley Dahir, R.A., Sr. Director, Quality Control & Construction Support
María A. Gómez, P.E., LEED A.P., Senior Director, A/E In-House Design
George D. Roussee, P.E., LEED A.P., Director, Technical Standards
Stacey Spann-Thom, Director, Operations Support

Consultants:

SUPER STRUCTURES
ENGINEERS ARCHITECTS

SHENY ENGINEERING
39 US 46E, SUITE 802, FREEBORO, NJ 07808
TEL 212 505 1833
FAX 212 505 1726

32 AVENUE OF THE AMERICAS
NEW YORK